

SPECIÁLIS 1 ÉS HÁROM FÁZISÚ VILLAMOS MO

Főfázis											
sz.	Típus	telj. W	áram- felv. A	tek. rend- szer	kapcs. jele	tek. száma	t. láb sz	lépés	menet szám	huzal Ø	elle- áll- óhm
39	OKC 3-2/12 OKC 1-2/12F 220V automata mosógép	230	3,7	kon- cent- rikus	soros	2	1	1-12	38	1x 0,7	5,
							2	1-10	38		
							3	1-8	38		
							4	1-6	38		
	mosó	37	1,7	egyré- teges koszorú	soros	12				1x 0,45	3
								1-3	190		
40	LU 532 B7e 220V fűnyíró	280	2,1	kon- cent- rikus	soros	2	1	1-10	54	1x 0,5	13
							2	1-8	108		
							3	1-6	108		
41	DZ 732 K7n1 220V belsőfékes motor centrifugához	220 felv.	1,2	kétré- teges koszorú	soros	2x 6 láb				1x 0,6	13
								1-11	50		
42	DZ 732 K7n1 220V belsőfékes motor centrifugához	210 felv.	1,0	kon- cent- rikus	soros	2	1	1-12	78	1x 0,6	12
							2	1-10	78		
							3	1-8	78		
							4	1-6	78		
43	HZM 80C-2/421 380/220V motor vízszivattyúhoz	1500	3,35	kétré- teges koszorú	soros	6	1	1-11	27	1x 0,55 +	4
							2	1-11	27		
							3	1-11	27		
							4	1-11	27		
44	OZM 80b2-2K/420 220V motor vízszivattyúhoz	750	5	kétré- teges koszorú	soros	2 x 6 láb				1x 0,8	4
								1-10	26		
45	OZM 80c2-2K/651 220V motor körfűrészhöz	1500	12	kon- cent- rikus	soros	2	1	1-12	22	2x 0,75 +	1
							2	1-10	22		
							3	1-8	22		
							4	1-6	22		